

# Oil Field Environmental Incident Summary

**Incident:** 20160524080149      **Date/Time of Notice:** 05/24/2016 08:01

**Responsible Party:** SM ENERGY COMPANY

**Well Operator:** SM ENERGY COMPANY

**Well Name:** L. JOHNSON 4-30HN

**Field Name:** BURG

**Well File #:** 30603

**Date Incident:** 5/23/2016

**Time Incident:** 11:00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 99

**Sec:** 30

**Qtr:**

**Location Description:**

**Submitted By:** Luke Studer

**Received By:**

**Contact Person:** Luke Studer  
PO BOX 7168  
BILLINGS, MT 59103-7168

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 3 Mile

**Distance Nearest Water Well:** 3 Mile

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine	4	Barrels	3	Barrels	3	barrels
Other					0	barrels

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 5/26/2016

**Clean Up Concluded:** 5/23/2016

**Risk Evaluation:**

None.

**Areal Extent:**

N/A

**Potential Environmental Impacts:**

None.

**Action Taken or Planned:**

Vac truck was able to recover 3 barrels of water. Contaminated soil will be taken to an approved disposal.

**Wastes Disposal Location:** Recovered water and contaminated soil to be taken to an approved disposal.

**Agencies Involved:**

**Updates**

**Date:** 5/24/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a truck overflow, remained within facility diking according to the report. NDIC retains oversight.